



Packaging Materials Included: return label, pouch with documents for U.S. Customs, box, and 1 large air sleeve.



Insert device into opening of air filled sleeve.



Insert the air filled sleeve into the box.



Insert power adapter and cable into the box.



Secure box with 2" shipping tape (not provided)



Affix the return label to the box.



Affix the pouch with documents for U.S. Customs to the box.



Drop your packaged device off at any FedEx Location